Respected Sir

Herewith I attached the EB shifting photos of my site before and after, in the before the EB lines are crossed the mid of our filed as per the TNEB guidance and as per the norms now we shift the EB lamp post as per the road path.

So kindly request you to forward the file further processing.

Before Shifting





After Shifting








EB LINE AFTER SHIFTING













GPS Map Camera

Thalaivasal, Tamil Nadu, India 🇮🇳

3/95, Poonjolai Thottum, Puthur (po), Thalaivachal Tk, Dt, Thalaivasal, Tamil Nadu 636112, India

Lat 11.620538° Long 78.780769°

09/09/2025 05:42 PM GMT +05:30

GPS Map Camera

Thalaivasal, Tamil Nadu, India 🇮🇳

3/95, Poonjolai Thottum, Puthur (po), Thalaivachal Tk, Dt, Thalaivasal, Tamil Nadu 636112, India

Lat 11.620535° Long 78.780771°

09/09/2025 05:41 PM GMT +05:30

GPS Map Camera

Thalaivasal, Tamil Nadu, India 🇮🇳

3/95, Poonjolai Thottum, Puthur (po), Thalaivachal Tk, Dt, Thalaivasal, Tamil Nadu 636112, India

Lat 11.620521° Long 78.780792°

09/09/2025 05:41 PM GMT +05:30