SITE DRONE PHOTO & GPS IMAGES

Dear Sir/ Madam,

We have already completed the EB pole shifting in accordance with TNEB norms. Initially, the EB pole was located at the center of the road area. We applied for the pole shifting process through the TNEB portal, submitted the required application, and paid the prescribed shifting fees.

Following this, a site inspection was conducted by the authorities, and the final shifting charges were confirmed. The pole has now been successfully relocated from the center of the road to the roadside area.

This relocation does not affect the plot area, and the LT line can now be utilized for residential electricity supply. We have also submitted the application copy and receipt as supporting documents.

Additionally, we have enclosed drone images and site photographs for your reference.

We kindly request you to review our submission and grant RERA approval.

Thank you.

Regarding

Jayabharath Homes Pvt Ltd

T.Naveen Kumar

9655210940

SITE DRONE PHOTO & GPS IMAGES



SITE DRONE PHOTO & GPS IMAGES



SITE DRONE PHOTO & GPS IMAGES



SITE DRONE PHOTO & GPS IMAGES





SITE DRONE PHOTO & GPS IMAGES

